

SECRET

DPD 4509-59

1 July 1957

MEMORANDUM FOR: Chief, Materiel Branch, DPD

SUBJECT: Service Bulletin Compliance

Request immediate action be taken to obtain the necessary parts as may be required to comply with the Service Bulletin attached hereto. Sufficient parts for three 295 Hellos and one 260 Hello should be procured. It should be noted that these bulletins should be complied with not later than the next 100 hour inspection and for those aircraft committed in support of Project [redacted] compliance prior to departure is desirable.

25X1

[redacted]
Acting Chief, Air Section, DPD

25X1

Attachments - 2

Service Bulletin #20

Service Bulletin #254A

DPD/AS [redacted]

25X1

Distribution:

Orig. & 1 - Addressee

2 - DPD/AS

1 - DPD/RJ

SECRET

25 YEAR RE-REVIEW